

FIG. 1




FIG. 2




FIG. 3




FIG. 3a




FIG. 3b




FIG. 3c





FIG. 4






FIG. 6




FIG. 7




FIG. 8




FIG. 9




FIG. 10




FIG. 11




FIG. 12




FIG. 13




FIG. 14




FIG. 15




FIG. 16






FIG. 18




FIG. 19




FIG. 20




FIG. 21




FIG. 22




FIG. 23a




FIG. 23b




Fig. 24


[illegible]

FIG. 25




FIG. 26




FIG. 27




FIG. 28




FIG. 29




FIG. 30




FIG. 31





FIG. 32






FIG. 33




FIG. 34




FIG. 35




FIG. 36




FIG. 37




FIG. 38




FIG. 39




FIG. 40




FIG. 41




FIG. 42





FIG. 43






FIG. 45




FIG. 46




FIG. 47




FIG. 48




FIG. 49




FIG. 50




FIG. 51




FIG. 52




FIG. 53




FIG. 54




FIG. 55




FIG. 56




FIG. 57






Fig. 58






FIG. 61




FIG. 62




FIG. 63




FIG. 64




FIG. 65




FIG. 66




FIG. 67




FIG. 68




FIG. 69




FIG. 70




FIG. 71




FIG. 72




FIG. 73




FIG. 74




FIG. 75




FIG. 76




FIG. 77




FIG. 78




FIG. 79




FIG. 80




FIG. 81




FIG. 82




FIG. 83




FIG. 84




FIG. 85




FIG. 86





FIG. 87



Vitrinite Reflectance (%)

FIG. 88





FIG. 89





T014240" 244T-1350




FIG. 92




FIG. 93

FIG. 94




FIG. 94




FIG. 95




FIG. 96




FIG. 97




FIG. 98




FIG. 99




FIG. 100




FIG. 101




FIG. 102




FIG. 103




FIG. 104




FIG. 105




FIG. 106




FIG. 107




FIG. 108




FIG. 110




FIG. 110




FIG. 111




FIG. 112




FIG. 113




FIG. 114


[illegible]

FIG. 115




FIG. 116




FIG. 117




FIG. 118




FIG. 119




FIG. 120




FIG. 121





FIG. 122






FIG. 124




FIG. 125




FIG. 126




FIG. 127




FIG. 128




FIG. 129

FOH240" 244F1860




FIG. 130




FIG. 131




FIG. 132




FIG. 133




FIG. 134




FIG. 135